



15 Tarragon Place, Bradley Stoke
Bristol BS32 8TP
Telephone: 0117 979 1704
E-mail: info@weldinginspectionsservices.com
www.weldinginspectionsservices.com

WELDING INSPECTION SERVICES LTD

VISUAL INSPECTION REPORT

Ref. No. : WIS/F5

Issue 1

Welding Inspection Services Ref No : **2016 / 25582**

GENERAL INFORMATION :

Client :	Vertical Extreme	Sheet No :	1 of 1
Location :	Bristol	Order No :	N Harrington
Inspector :	N Munford	Date of Test :	03/08/2016
Qualification/Number :	CSWIP Visual		
Item Inspected :	One Off Climbing Wall		
Item Identification :	MW4-ANN		
Drawing Number :	Not Required		
Material and Dimension :	As Per Drawing		
Extent of Inspection :	100% Visual Of All Accessible Welds		
Stage of Test :	In Service Inspection		
Surface Conditions :	As Welded		

TECHNIQUE :

Inspection Standard :	WIS-NDT-VT-01 Issue 2 & BS EN ISO 17637 : 2011
Viewing Conditions :	White Light 1000 Lux
Examining Equipment Used :	Inspection Kit One
Acceptance Standard :	BS EN 5817 : 2014 Level B

RESULTS :

A 100% Visual Inspection Was Carried Out By The Above Named Inspector. The Climbing Wall Was Acceptable To Specification .

ONE OF CLIMBING WALL M4W-ANN - ACCEPT

Name : Paul Robinson
PCN Level 2 & 3
Date : 15th July 2016

Signature :

